

CHANGES TO CODE



HOME ELEVATOR SAFETY NOTICE

In 2016, the ASME A17.1 2016 Section 5.3 Residential Elevator Safety Code was updated in response to safety concerns regarding the well-being of small children.



Contact:

Country Home Elevator
1549 E. 559th Rd.,
Brighton, MO 65617

Email: info@chelevator.com

Phone: 417-376-4009

Toll Free: 800-898-5090


 **COUNTRY HOME**
Elevator & Stair Lift

CountryHomeElevator.com



 **COUNTRY HOME**
Elevator & Stair Lift

The Concern



Some elevators installed prior to 2016 may contain gaps between the Elevator Gate and Hoistway access door that can be a **safety hazard to small children.**

Country Home Elevator takes this matter seriously. Providing state of the art solutions to reduce or restrict the space.

NOTICE

To comply with the ASME A17.1 2016 Section 5.3 Code, the gaps on all elevators we service shall **not exceed 4 inches.**

Your Options

If your personal home elevator has a gap of more than 4 inches, Country Home Elevator has options to **make your home elevator safer.** Contact us to learn more about the following options:

	PRICE PER DOOR
1. Plywood sheets on the hoistway doors at all landings. Free material and installation instructions. Call for details.	Free Materials
2. Plywood with custom size and finishes	\$78
3. Plastic & metal angle baffles screwed to all doors	\$149
4. Space guard door baffle	\$149
5. Full height baffles applied to all doors *Full code compliance	\$225
6. Light rays on each doorway	Site Specific Quote
7. Flush door jambs and doors *Full code compliance	Site Specific Quote
8. Custom solutions quoted per each door	Site Specific Quote
9. Caution stickers	FREE